





THE UNIQUENESS OF THE ZONING LOT (CORNER LOT, THRU LOT AND INTERIOR LOT CONDITIONS EXISTED WITHIN THIS LOT), AND THE REQUIREMENTS OF THE SCHOOL HELPED TO INFORM THE DESIGN OF THE BUILDING. THE CORNER LOT PORTION OF THE LOT OFFERED US THE BEST OPPORTUNITY TO EXPAND VERTICALLY, BASED ON AREA AND HEIGHT REGULATIONS.



New Addition

EXISTING INTERIOR BUILDING CONDITIONS


BUILT IN 1956, THIS BUILDING PREVIOUSLY HOUSED CITY OFFICES, HOWEVER IT SAT VACANT FOR SEVERAL YEARS BEFORE UNDERGOING THIS RENOVATION. ONE OF THE 1ST CHALLENGES FACED WAS THAT THERE WERE 3 EXISTING "SECTIONS" OF THE BUILDING, WHICH WERE ONCE 3 SEPARATE BUILDINGS, BUILT AT SEPARATE TIMES, AND LATER MERGED TOGETHER. THESE WERE ALL BUILT AT DIFFERENT TIMES, WITH DIFFERENT STRUCTURAL SYSTEMS, DIFFERING FLOOR HEIGHTS/LEVELS AND DIFFERENT FIRE RATINGS.












EXTERIOR FACADE DEVELOPMENT THE CONDITION OF THE EXISTING BUILDING FAÇADE WAS POOR, AS WALLS WERE CRACKED, FALLING DOWN, AND BOWING OUT. AS DEMOLITION ADVANCED, IT BECAME APPARENT THAT THE FRONT WALL OF THE BUILDING ALONG CEDAR LANE WAS NOT STRUCTURALLY STABLE. THE DECISION WAS MADE THAT DEMOLITION AND RECONSTRUCTION OF THE WALL WAS NECESSARY. STRUCTURAL STABILITY AND INCREASED ENERGY EFFICIENCY WERE ACHIEVED BY DOING THIS.







PHASED OPENING PROCESS

DUE TO THE STRICT TIMELINE OF THE PROJECT AND OUR CLIENT'S NEEDS OF HAVING THE LOWER 2 FLOORS OPEN AND FUNCTIONAL AS SOON AS POSSIBLE, WE HAD TO GET THE ENTIRE STRUCTURE ERECTED, AND THE LOWER FLOORS FINISHED AT THE SAME TIME BEFORE WE WERE ABLE TO OPEN. COORDINATION BETWEEN ALL TRADES AND CITY AGENCIES ON THE PROJECT WAS NEEDED AND OBTAINED AND WE WERE ABLE TO ACHIEVE OUR GOAL.












architect LLC





<u>DESIGN INSPIRATION</u>

THE BOY'S PREP BIRD LOGO WAS A DRIVING FORCE BEHIND MUCH OF THE DESIGN OF THE EXTERIOR OF THE BUILDING. WE WANTED TO DECONSTRUCT THE SHAPES THAT MADE UP THE BIRD, AND INCORPORATE THEM INTO OUR DESIGN, BOTH ON THE INTERIOR AND EXTERIOR.























THE NEW GYM WAS ENVISIONED TO BE ADDED TO THE EXISTING ROOF OF THE 1 STORY "SECTION C" PORTION OF THE BUILDING. THE EXISTING ROOF STRUCTURE CONSISTED OF WOOD JOISTS, AND WAS NOT ADEQUATE FOR THE STRUCTURAL AND FIRE RESISTANCE REQUIREMENTS OF THE PROPOSED NEW CONSTRUCTION. THE EXISTING ROOF WAS TAKEN OFF AND REPLACED WITH A NEW FLOOR STRUCTURE, WHICH IS NOW THE FLOOR OF THE GYM. A UNIQUE OPPORTUNITY PRESENTED ITSELF TO CAPTURE AN ABUNDANCE OF NATURAL LIGHT THRU THE USE OF SKYLIGHTS IN THE CEILING OF THE NEW GYM.

GYMNASIUM

DEVELOPMENT



architect LLC

